



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

Lowell P. Braxton  
Division Director

1594 West North Temple, Suite 1210  
PO Box 145801  
Salt Lake City, Utah 84114-5801  
801-538-5340  
801-359-3940 (Fax)  
801-538-7223 (TDD)

March 5, 1998

Gary Gray  
Genwal Resources, Inc.  
P. O. Box 1420  
Huntington, Utah 84528

Re: Requirement to Correct Plan Deficiencies Associated with Highwall Elimination, Genwal Resources, Inc., Crandall Canyon Mine, ACT/015/032, Folder #3, Emery County, Utah

Dear Mr. Gray:

During the last two years one of the main topics of oversight has been Highwall Elimination and Retention as a Part of Approximate Original Contour Restoration. The joint DOGM/OSM oversight team has evaluated this element under the primary oversight objective of determining whether minesite reclamation is successful. Surveys were sent to the mine operators asking for information on highwalls, mine plans were reviewed, field visits were conducted and an inventory compiled which identified those mine sites that had permit deficiencies associated with highwall reclamation.

In the highwalls inventory, the team found that 7 of the 35 mines (20 percent) in Utah have permit deficiencies relating to highwall reclamation. These deficiencies include (1) those situations where the permits show parts of post May 3, 1978, highwalls that will be retained contrary to the requirements of Utah's program, and (2) other situations where the permits are not clear as to what extent pre and post May 3, 1978, highwalls will be eliminated.


The Crandall Canyon Mine was one of those identified as having permit deficiencies. In order to resolve the deficiencies, you must revise your reclamation plan to address the elimination of highwalls as a function of Approximate Original Contour Restoration. It is suggested that you provide maps and cross sections of the highwall areas in enough detail to show how they will be reclaimed (cross sections perpendicular to the portal areas are recommended). The text also needs to discuss complete elimination for all post May 3, 1978 highwalls, and elimination, to the extent practical, using all reasonably available spoil for pre May 3, 1978 highwalls. Enclosed is a copy of the Division's Directive on Approximate Original Contour Requirements which may aid you in preparing your response.

Page 2  
Gary Gray  
ACT/015/032  
March 5, 1998

We have attempted to tie the schedule for correcting your plan to some other major permitting action that may be happening at the mine as well as trying to space out the reviews to accommodate DOGM's time frames. The schedule for the Crandall Canyon Mine was discussed with you and it was determined to correct the plan in conjunction with the Mill Fork lease application or February 1, 2000, whichever comes first.

Please provide the required amendment by no later than the February 2000 date. We recognize that this is quite far into the future, but encourage you to start correcting the problem now so that you will have any necessary field work done and adequate information compiled by the time your submittal is due. If you have any questions, don't hesitate to call. We look forward to hearing from you.

Sincerely,



Daron R. Haddock  
Permit Supervisor

jb  
Enclosure: Division's Directive on ...Contour Requirements  
cc: Jim Fulton, OSM, w/o  
Mary Ann Wright, DOGM, w/o  
Joe Helfrich, DOGM, w/o  
Price Field Office, w/o  
NAWP60DOCS\HIWALLTR.GEN